

USER: Hard-cool mine

DESCRIPTION OF THE PROBLEM: A pump's rotor was effaced (in a level making it impossible to function) in the plant sewage treatment station of Meat Plant.

DESCRIPTION OF THE REPAIR: The rotor was sanded and defatted with *Chester Cleaner*. The screw-shaped rotor was reconstructed with the help of *Chester Metal Ceramic T* and *Chester Metal Ceramic F*.

ACHIEVED EFFECTS: The rotor was successfully regenerated thanks to *Chester Metal Ceramic T* and *Chester Metal Ceramic F*.

